



Port & Company[®] Tall 50/50 Cotton/Poly T-Shirts PC55T

PRODUCT MEASUREMENTS

	LT	XLT	2XLT	3XLT	4XLT
Chest	22	24	26	28	30
Sleeve Length	20 3/4	21 3/4	22 3/4	23 3/4	24 3/4
Body Length at Back	33	34	35	36	37

CHEST

Measured across the chest one inch below armhole when laid flat.

SLEEVE LENGTH

Start at center of neck and measure down shoulder, down sleeve to hem.

BODY LENGTH AT BACK

Measured from high point of shoulder from the back.